0046

Daron Haddock

From: Daron Haddo To: OGMCOAL

**Date:** 11/17/2009 7:49 AM

**Subject:** Fwd: Northwater Springs Inspection

Place: OGMCOAL

Attachments: Comments to Ingrid Wieser.doc; NWaterSpringInspection.pdf

>>> Ingrid Wieser 11/16/2009 5:18 PM >>>

A11-

Please see the attached DOGM inspection report # 2164 and comments from Leland Roberts regarding the SUFCO site visit to Northwater springs on October 19th.

Leland- Thank you for providing the clarifications.

Ingrid Wieser

>>> "Roberts, Leland" <<u>LRoberts@archcoal.com</u>> 11/13/2009 2:28 PM >>> Ingrid,

Sufco would like to address some items in the trip report that you sent out. Please find attached a list of items that we would like to clarify or comment on. Please feel free to contact me with any questions that you might have.

Thank you, Leland

Leland Roberts Environmental Engineer CFC, Sufco Mine (435) 286-4483

<<Comments to Ingrid Wieser.doc>>
\*\*\*\*\*\*\*\* Email Disclaimer \*\*\*\*\*\*\*\*

The information contained in this e-mail, and in any accompanying documents, may constitute confidential and/or legally privileged information. The information is intended only for use by the designated recipient. If you are not the intended recipient (or responsible for delivery of the message to the intended recipient), you are hereby notified that any dissemination, distribution, copying, or other use of, or taking of any action in reliance on this e-mail is strictly prohibited. If you have received this e-mail communication in error, please notify the sender immediately and delete the message from your system.

Outgoing co410002

R\_

1. Permits, Change, Transfer, Renewal, Sale

5<sup>th</sup> Sentence that starts with, "In accordance" Sufco submitted a letter to Mr. John R. Baza, Division Director Division of Oil, Gas and Mining and Mr. Jerry D. Olds, P.E. Utah State Engineer Utah Division of Water Rights on November 14, 2006 challenging the findings of material damage.

6<sup>th</sup> sentence that starts with "Piezometers established" the water level has lowered

in depth between 2 and 20 feet below the surface.

7<sup>th</sup> Sentence that starts with "Several strategies" Sufco proposed or attempted the mentioned items on a pilot scale to evaluate their potential for restoring the surface flow of the springs.

8<sup>th</sup> Sentence that starts with "An exploratory" Castlegate is one word.

### 4.d Hydrologic Balance: Water Monitoring

2<sup>nd</sup> paragraph, Plate 7-3 does not show Pines 105 or 310/311 as part of a perennial stream reach. It is not a perennial stream but a wet spring discharge area.

# 9. Protection of Fish, Wildlife and Related Environmental Issues

2<sup>nd</sup> paragraph 3<sup>rd</sup> sentence that starts with "Canyon Fuel Co." Sufco drilled 5 wells in 2009 with completed depths of 168 to 228 feet below the surface. Water levels in the wells are approximately 150 feet below the surface. The aquifer is approximately 55 feet below the elevation of the Pines 105 spring.

2<sup>nd</sup> paragraph 4<sup>th</sup> sentence that starts with "As a result" Sufco is proposing to complete wells near the spring sites, Pines 105, Joes Mill Pond, and the 310/311 area, not

at each of the exploratory wells drilled.

3<sup>rd</sup> paragraph, Sufco would like to note that subsurface soils are not yet dry. This is demonstrated by the presence of water in many of the piezometers as well as vegetation (willows) that has been documented within the area that has been excluded from grazing at Pines 105.

3<sup>rd</sup> paragraph 3rd sentence that starts with "Leland Roberts" The white Pipe (piezometer) initially moved as one with the bedrock that was subsided, on average the piezometers have moved approximately .6 feet since installation. The black pipe (casing) has moved in addition to subsidence, approximately .46 feet, for a total average elevation change of 1.06 feet. This demonstrates that some of the soils in the area are no longer saturated causing them to collapse. This is due both to climatic conditions (drought) as well as the loss of surface flow in Pines 105 and 310/311 area.

#### 14. Subsidence Control

Sufco is unclear as to the location of the surface water losses that this section refers to. Loss of surface flow in the main stem of the East Fork of Box Canyon was repaired by the summer of 2007. Hydrologic monitoring demonstrates that surface flows have returned to pre-mining conditions.



#### State of Utah

### Department of Natural Resources

MICHAEL R. STYLER
Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

#### Representatives Present During the Inspection: Ingrid Wieser Environmental Scientist II Daron R. Haddock Environmental Manager USFS Tom Lloyd Ferron-Price District Geologist USFS Dale Harber Forest Geologist Marc Stillson Regional Engineer Company Mike Davis Other Erik Petersen Priscilla Burton Environmental Scientist III OGM Chris D. Hansen Environmental Manager Company

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SUFCO MINE

Address: 397 S 800 W, SALINA UT 84654

County: SEVIER

Total Disturbed
Phase I
Phase II
Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

25,292.43 Total Permitted

**Current Acreages** 

### Mineral Ownership

Other

# Types of Operations

Reprocessing

**Inspection Report** 

C0410002

TECHNICAL

Monday, October 19, 2009

10/19/2009 10:00:00 AM

10/19/2009 3:30:00 PM

Tuesday, October 13, 2009

Accepted by: jhelfric

10/29/2009

Permit Number:

Inspection Type:

Inspection Date:

Start Date/Time:

End Date/Time:

Last Inspection:

Weather: Sunny (windy) 65 F

InspectionID Report Number: 2164

Inspector: \_\_\_

✓ Feder	al 🗹	Underground
✓ State		Surface
Oount	у 🗆	Loadout
Fee		Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Representatives from DOGM, USFS, DWRi, Emery Stock Growers Association., SUFCO mine, Canyon Fuel Co., LLC and Peterson Hydrologic Consulting met to evaluate conditions at two spring sites on the Manti LaSal: North Water Springs and Joes Mill, both of which lost surface water seepage due to subsidence from underground mining. The mine proposes to install wells into bedrock below the level of the drained alluvial aquifer and pump water to the surface to provide water for livestock and wildlife. The excess will be used to recreate the riparian area at the spring. In addition to those persons listed above, John Wytannis, Acting District Ranger, John Heeley, and Lance Sudweeks from the Manti LaSal Nat Forest; Morris Sorenson and Russ Jensen from the Emery Stock Growers Association; and Leland Roberts from SUFCO were present.

Inspector's Signature:

Jugnd Muses

Date Wednesday, October 21, 2009

Inspector ID Number:

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining. 1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

**Inspection Continuation Sheet** 

Permit Number: C0410002 Inspection Type: TECHNICAL

Inspection Date: Monday, October 19, 2009

Page 2 of 4

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- Poi FACTIAL inspections crieck only the elements evaluated.
   Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
   Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		<b>~</b>	
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>		<b>V</b>	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues	<b>V</b>		<b>✓</b>	
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control	<b>V</b>		<b>V</b>	
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check	· 🗆			
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0410002 Inspection Type: TECHNICAL

Inspection Date: Monday, October 19, 2009

Page 3 of 4

#### 1. Permits, Change, Transfer, Renewal, Sale

North Water spring is a developed spring located in the East Fork of Box Canyon above panel 5L of SUFCO's Pines Tract. North Water spring was undermined in 2005. Joe's Mill Pond is a manmade structure developed to capture flow from an adjacent spring. In 2006 the springs went dry and the Division made a Finding of Material Damage (Outgoing/0013.pdf). In accordance with the finding of material damage, SUFCO provided a plan for mitigation (MRP, App. 7-22). Piezometers established that the water level in the alluvium had lowered to a depth of 20 ft below the surface. Several strategies to recapture the water in the lowered water table of the alluvium were attempted (a grout curtain; collection in perforated pipe; and pumping from a down canyon spring to the troughs), but none was successful in restoring the springs. An exploratory drilling program was undertaken to evaluate the availability of water from the Castle Gate Sandstone, the bedrock below the alluvium (App. 7-22, updated 2009).

During this field meeting Canyon Fuel Co., LLC explained the results of the 2009 drilling program and their proposal to develop water supply wells in the Castlegate Sandstone to pump water to the troughs and pond.

### 4.d Hydrologic Balance: Water Monitoring

Plate 7-3 shows the location of springs. North Water Spring and Joes Mill Pond were historically used by cattle. Both springs were overlooked in the 1981 inventory filed with the DWRi. The USFS will file dilligence claims with DWRi for both springs to secure the water rights.

North Water Spring (Pines 105) has been monitored by SUFCO and data is available in the Division's water database. Plate 7-3 shows this spring as part of a perennial stream reach that is monitored.

Permit Number: C0410002 Inspection Type: TECHNICAL

Inspection Date: Monday, October 19, 2009

Page 4 of 4

# 9. Protection of Fish, Wildlife and Related Environmental Issues

In 2000 Emery Stock Growers, installed troughs on a ridge above the North Water canyon (elevation 8,422 ft.). They installed a water line and solar pump from the North Water spring (elevation 8,327 ft.) to bring the water up to the troughs. Flow at the troughs was measured at 5-7 gpm. The cattle stay an average of 15 days/year in this location, according to Morris Sorenson.

Recent (2009) slug tests and re-evaluation of previous piezometric data have lead the investigators to conclude that the alluvial sand beds are discontinuous, and intermittent with (less permeable) organic layers providing a patchwork of water in the alluvium. Investigators concluded that the most productive means of resupplying water to the alluvium is from a deeper source. Canyon Fuel Co. recently drilled two exploratory wells 143 ft to 150 ft. below the surface, into bedrock and found an aquifer, 55 ft below the elevation of the North Horn spring (see App. 7-22 for locations of wells and other details of the drilling program). As a result of this exploratory drilling, Canyon Fuel Co., LLC. proposes to complete a water supply well near each spring site and to install solar panels or wind mills to pump approximately 5 gpm from the bedrock aquifer (below the alluvium) up to the surface to fill the water troughs and the pond. Overflow will be returned to North Water Canyon. An amendment to the Mining and Reclamation Plan will be forthcoming.

According to the USFS, the ground surface has lowered considerably since installation of the 2006 piezometers due to the drying of the organic soils. Since highly organic soils (peat) become hydrophobic and do not rewet easily, the USFS is hopeful that these organic layers may act as an aquitard to keep the water at the surface when it is replaced by pumping. Leland Roberts, SUFCO Mine, confirmed that the piezometers do illustrate the effects of draining the alluvium due to the movement of the outer, black pipe (installed within the alluvium which has lowered) against the stationary, inner, white pipe (installed on bedrock which has not moved). The elevation of the piezometer in the vicinity of northwater spring was lowered 1.8 ft. between 2006 - 2008.

#### 14. Subsidence Control

In addition to the North Water and Joes Mill pond springs, subsidence created surface water losses in a stream section of the East Fork of Box Canyon (Pines Tract). (No determination of material damage was made on the East Fork of Box Cyn loss.) Stipulation #17 of the federal lease requires that impacted water sources be replaced. SUFCO and the Emery Stock Growers Association and the USFS are cooperatively working towards a common goal of water replacement. The Stock Growers request that they continue to be included in the dialogue between agencies and the mine operation.